Joe Lemay/R1/USEPA/US

11/28/2005 09:28 AM

To Frank Gardner/R1/USEPA/US@EPA, Sharon Fennelly/R1/USEPA/US@EPA

cc Susan Scott/R1/USEPA/US@EPA

bco

Subject Fw: 21E documents related to the Arsenic Contamination on the Riley Tannery property

Here are the DEP audit findings at JJ Riley in 1996, and Maggoire Corporation's follow-up investigations at JJ Riley by their contractor 21E Corporation. It appears their investigations did not include the drainage ditch, north of the drainage ditch where there is tannery waste, and the flat area at the bottom of the ridge (where storm flows would accumulate as water backs up from railroad culvert). It appears 21E Corporation identified these areas as "heavily wooded areas (inaccessible)" in their investigation plan.

Arsenic was identified at TP-1 near Wildwood Avenue (Southwest corner of the Site). At the north-central portion of the Site (south of the current drainage ditch and surface water detention basin), the TP-12 had arsenic, and TP-16 had chromium and arsenic with significant tannery waste. TP-16 uncovered blue soils with chromium at 87,500 ppm. All the elevated levels of arsenic and chromium were removed from the property. See figure associated with 21E audit findings completion statement 8-14-96.

Joe-

---- Forwarded by Joe Lemay/R1/USEPA/US on 11/28/2005 08:53 AM -----



"Moore, Jeffrey" <JMoore@TechLawInc.com> 11/22/2005 01:18 PM

To Joe Lemay/R1/USEPA/US@EPA

cc "Cote, Heather" < hcote@TechLawInc.com>

Subject 21E documents related to the Arsenic Contamination on the Riley Tannery property

Joe,

Heather asked me to forward the attached documents related to the Arsenic Contamination on the Riley Tannery property.

If you have any questions please contact Heather.

Heather's cell - 339-987-0797

Thanks, Jeff

Jeffrey T. Moore

Scanning Supervisor

TechLaw, Inc.

90 Canal Street Suite 303 Boston, MA 02114 Tel: 617-720-0320 ext

Tel: 617-720-0320 ext. 160 Fax: 617-720-0321

jmoore@techlawinc.com

www.techlawinc.com

